




Xpedite

ROOTING GUIDE

v1.0



Get your device ready for rooting

1. Turn on USB debugging

Go Apps > Settings > Developer Options. If Developer options menu is not visible on your device, go Apps > Settings > About Device and scroll down to the **Build Number**. Now tap it five times and you should see a notification saying **Developer mode has been enabled**. Now turn on **USB debugging**.



2. Switch your device in download mode


- Power off
- Hold Volume down + Home + Power until you will see the following screen.



3. Press volume up

You should see the following screen.

Rooting



1. **Connect** your device to your PC via USB cable.
2. **Run** the .exe file (the one you previously downloaded).
3. **Push PDA button**, select the .tar.md5 file and push Start. Flashing your device will take a little while.

Gongratulations you have now sucessfully rooted your device!

Thank You for choosing Xpedite!

For more information about Xpedite and other X-TEL products please visit:

www.x-tel.com